The heat pump system must be charged in cooling only with a recommended subcooling of 10° F at the liquid service valve of the outdoor unit.

RCTA-B060 Replacement Coil

Coil Dimensions




Figure 1

RCTA-B, Wet Coil Pressure Drop

Airflow CFM	1200	1400	1600	2000
Inches, WC	0.18	0.22	0.25	0.32

Table 2